

Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 1 of 7 sheets




FIG. 1

Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 2 of 7 sheets





FIG. 2

Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 3 of 7 sheets



Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 4 of 7 sheets





FIG. 4

Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 5 of 7 sheets



Frequency (HZ)

FIG. 5

Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 6 of 7 sheets




FIG. 6

Reply to Office Action of May 26, 2005 Reply Mailed: 11/23/2005

Group Art Unit: 2651 Telephone: 360-527-1400

Replacement Sheet 7 of 7 sheets




FIG. 7